

00839.000466.



PATENT

Cafe \$

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

JINSHO MATSUYAMA

Appl. No.: 10/627,923

Filed: July 28, 2003

For: METHOD AND APPARATUS FOR
MEASURING PHOTOELECTRIC
CONVERSION DEVICE, AND
PROCESS AND APPARATUS FOR
PRODUCING PHOTOELECTRIC
CONVERSION DEVICE

U.S. Patent No.: US 6,946,858 B2

Issued: September 20, 2005

) Examiner: Vinh P. Nguyen

) Group Art Unit: 2829

) January 5, 2006

Certificate

JAN 10 2006

of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

01/09/2006 JADDO1 00000003 6946858

100.00 OP

01 FC:1811

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

JAN 11 2006
JAN 11 2006

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



John A. Krause
Attorney for Patentee
Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
NY_MAIN 543860v1

JAN 11 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 6,946,858 B2

DATED : SEPTEMBER 20, 2005

INVENTOR(S) : JINSHO MATSUYAMA

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 12, "as" should read --as a--; and
Line 28, "wherein" should read --wherein an--.

COLUMN 2

Line 12, "entire" should read --entire area--.

COLUMN 3

Line 33, "enspective" should read --inspective--.

COLUMN 4

Line 16, "respect" should read --respect to--;
Line 38, "device" should read --device,--;
Line 39, "large" should read --large,--;
Line 41, "film" should read --film,--;
Line 47, "FIG. 7" should read --FIG. 7,--;
Line 66, "condition" should read --conditions--; and
Line 67, "unstable" should read --unstable,--; and "sunlight" should read --sunlight,--.

COLUMN 5

Line 2, "apparatus" should read --apparatus,--;
Line 3, "characteristics" should read --characteristics,--;
Line 4, "light" should read --light,--; and
Line 5, "unstable" should read --unstable,--; and "sunlight" should read --sunlight,--.

COLUMN 8

Line 3, "description" should read --a description--;
Line 49, "can" should read --can be--; and
Line 67, "those" should read --whose--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_MAIN 543860v1

PATENT NO. US 6,946,858 B2

No. of add'l. copies
@ 30¢ per page



JAN 11 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 6,946,858 B2

DATED : SEPTEMBER 20, 2005

INVENTOR(S) : JINSHO MATSUYAMA

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9

Line 1, "respect" should read --respect to--;
Line 20, "an" should read --in--;
Line 25, "intention" should read --invention--; and
Line 58, "there" should read --where--.

COLUMN 11

Line 25, "other" should read --another--;
Line 42, "Mismatch" should read --mismatch--;
Line 53, "Qs(λ);" should read --Qs(λ):--; and
Line 56, "where" should read --with--.

COLUMN 12

Line 9, "current voltage" should read --current-voltage--.

COLUMN 13

Line 25, "ref rence" should read --reference--;
Line 42, "similar 3" should read --similar--; and
Line 63, "make" should read --taken--.

COLUMN 14

Line 2, "deviation" should read --of a deviation--;
Line 10, "possible" should read --possible to have--;
Line 26, "(6)" should read --(6).--;
Line 48, "means" should read --mean--;
Line 65, "lager." should read --larger.--; and
Line 67, "designed" should read --design--.

COLUMN 15

Line 6, "below" should read --below.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_MAIN 543860v1

PATENT NO. US 6,946,858 B2

No. of add'l. copies
@ 30¢ per page



JAN 11 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PATENT NO. : US 6,946,858 B2

DATED : SEPTEMBER 20, 2005

INVENTOR(S) : JINSHO MATSUYAMA

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16

Line 2, "pair" should read --a pair--;
Line 6, "measures" should read --measured--; and
Line 47, "made" should read --made to--.

COLUMN 17

Line 39, "be also" should read --also be--;
Line 64, "at" should read --at an--; and
Line 66, "thereafter" should read --thereafter--.

COLUMN 18

Line 5, "be always" should read --always be--;
Line 6, "be" should read --always--;
Line 7, "always and" should read --be--; and "refrain" should read --refrain from--; and
Line 13, "refraining" should read --refraining from--;
Line 26, "step, the" should read --step. The--; and
Line 41, "refrain" should read --refrain from--.

COLUMN 19

Line 21, "cells" should read --cells to--.

COLUMN 20

Line 54, "call" should read --cell--; and
Line 66, "be also" should read --also be--.

COLUMN 21

Line 5, "performed." should read --is performed.--;
Line 19, "aforesaid" should read --the aforesaid--; and
Line 61, "fired" should read --fixed--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_MAIN 543860v1

PATENT NO. US 6,946,858 B2

No. of add'l. copies
@ 30¢ per page

JAN 11 2006
JAN 11 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 6,946,858 B2

DATED : SEPTEMBER 20, 2005

INVENTOR(S) : JINSHO MATSUYAMA

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 22

Line 17, "expression" should read --expression is--.

COLUMN 25

Line 60, "Well" should read --well--; and
Line 63, "wide" should read --side--.

COLUMN 26

Line 26, "cmx42 cam" should read --cmx 42 cm,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_MAIN 543860v1

PATENT NO. US 6,946,858 B2

No. of add'l. copies
@ 30¢ per page



JAN 11 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 6,946,858 B2

DATED : SEPTEMBER 20, 2005

INVENTOR(S) : JINSHO MATSUYAMA

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 12, "as" should read --as a--; and
Line 28, "wherein" should read --wherein an--.

COLUMN 2

Line 12, "entire" should read --entire area--.

COLUMN 3

Line 33, "enspective" should read --inspective--.

COLUMN 4

Line 16, "respect" should read --respect to--;
Line 38, "device" should read --device,--;
Line 39, "large" should read --large,--;
Line 41, "film" should read --film,--;
Line 47, "FIG. 7" should read --FIG. 7,--;
Line 66, "condition" should read --conditions--; and
Line 67, "unstable" should read --unstable,--; and "sunlight" should read --sunlight,--.

COLUMN 5

Line 2, "apparatus" should read --apparatus,--;
Line 3, "characteristics" should read --characteristics,--;
Line 4, "light" should read --light,--; and
Line 5, "unstable" should read --unstable,--; and "sunlight" should read --sunlight,--.

COLUMN 8

Line 3, "description" should read --a description--;
Line 49, "can" should read --can be--; and
Line 67, "those" should read --whose--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,946,858 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

NY_MAIN 543860v1

→ _____
JAN 11 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only

PRINTER'S TRIM LINE

PATENT NO. : US 6,946,858 B2

DATED : SEPTEMBER 20, 2005

INVENTOR(S) : JINSHO MATSUYAMA

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9

Line 1, "respect" should read --respect to--;
Line 20, "an" should read --in--;
Line 25, "intention" should read --invention--; and
Line 58, "there" should read --where--.

COLUMN 11

Line 25, "other" should read --another--;
Line 42, "Mismatch" should read --mismatch--;
Line 53, "Qs(λ);" should read --Qs(λ):--; and
Line 56, "where" should read --with--.

COLUMN 12

Line 9, "current voltage" should read --current-voltage--.

COLUMN 13

Line 25, "ref rence" should read --reference--;
Line 42, "similar 3" should read --similar--; and
Line 63, "make" should read --taken--.

COLUMN 14

Line 2, "deviation" should read --of a deviation--;
Line 10, "possible" should read --possible to have--;
Line 26, "(6)" should read --(6).--;
Line 48, "means" should read --mean--;
Line 65, "lager." should read --larger.--; and
Line 67, "designed" should read --design--.

COLUMN 15

Line 6, "below" should read --below.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_MAIN 543860v1

PATENT NO. US 6,946,858 B2

No. of add'l. copies
@ 30¢ per page



JAN 11 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 6,946,858 B2

DATED : SEPTEMBER 20, 2005

INVENTOR(S) : JINSHO MATSUYAMA

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 16

Line 2, "pair" should read --a pair--;
Line 6, "measures" should read --measured--; and
Line 47, "made" should read --made to--.

COLUMN 17

Line 39, "be also" should read --also be--;
Line 64, "at" should read --at an--; and
Line 66, "thereafter" should read --thereafter--.

COLUMN 18

Line 5, "be always" should read --always be--;
Line 6, "be" should read --always--;
Line 7, "always and" should read --be--; and "refrain" should read --refrain from--; and
Line 13, "refraining" should read --refraining from--;
Line 26, "step, the" should read --step. The--; and
Line 41, "refrain" should read --refrain from--.

COLUMN 19

Line 21, "cells" should read --cells to--.

COLUMN 20

Line 54, "call" should read --cell--; and
Line 66, "be also" should read --also be--.

COLUMN 21

Line 5, "performed." should read --is performed.--;
Line 19, "aforesaid" should read --the aforesaid--; and
Line 61, "fired" should read --fixed--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

NY_MAIN 543860v1

PATENT NO. US 6,946,858 B2

No. of add'l. copies
@ 30¢ per page



JAN 11 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 6,946,858 B2

DATED : SEPTEMBER 20, 2005

INVENTOR(S) : JINSHO MATSUYAMA

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 22

Line 17, "expression" should read --expression is--.

COLUMN 25

Line 60, "Well" should read --well--; and
Line 63, "wide" should read --side--.

COLUMN 26

Line 26, "cmx42 cam" should read --cmx 42 cm,--.

MAILING ADDRESS OF SENDER:


FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,946,858 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

NY_MAIN 543860v1



JAN 11 2006